EPA Region 5 Records Ctr.

289620

CERCLIS EXECUTIVE SUMMARY

state, feel	5 E 04 0/ A0403
nesubraces	NEA
JA13 Worden had	() W/co
SUMMARY ON JULY	st 10-5-80
WINDSHIELD SURVEY	kes <u>no</u>

EPA ID# <u>981957608</u>		WINDSHIELD	SURVEY JA	YESNO
Original Company Name	: Avon Dump Site			/ -
Revised Company Name:			~ 	
Alias Names:			-	
Original X Address Corrected		county <u>063</u> County	Code 06	Cong. Dist.
Coordinates:	39° 45' 40"	Latitude086°	23 00 0	Longitude
Landfill Transporter X	Generator Other: None	Treatment, Sto	rage, Dispos	sal (TSD)
PRIORITY ASSESSMENT:	HIGHMEDIU	JM LOW X N	O FURTHER AC	CTION (NONE)
	State Accompanies	s Limited On State Invo	-site lvement	None
X P An inspection of	y Justification and ASIFolloothis property was	d State Comments Row-up SIRPSRPSRps	egarding: HRS 3, 1987, by	IDEM
personnel along with Dr. Thomas Terry, sur ever taken place on the inspection di State is recommending	perintendent, no du the property. id not reveal any o	umping of any haza evidence of dumpin	rdous materi	ials has
	STATE IN	VOLVEMENT		
C Preliminary AssesResponsi	ssmentsSite : ble Party Search			
* COMPLETE DOCUMENTS	(C) REVIEW DO	CUMENTS (R)		
Prepared by: Alan Front Activity Time: 16		Phone: 232-8931	Date	: 11/1/87

interest in the second of the second

EPA ID# 981957608

BEGENVED 19/2.
NOV 09 1587 . July 100 ... Land

CERCLIS EXECUTIVE SUMMARY

Pre-Remedial WINDSHIELD SURVEY! | X YES ___NO

Original Company Name: Avon Dump Site			
Revised Company Name:			
Alias Names:			
Original X Address Corrected	RR & School Yard Hendricks County 063 County Code 06 Cong. Dist.		
Coordinates:	39° 45' 40" Latitude 086° 23' 00" Longitude		
Landfill X	GeneratorTreatment, Storage, Disposal (TSD) Other: None		
PRIORITY ASSESSMENT:	HIGH MEDIUM LOW X NO FURTHER ACTION (NONE)		
CLASS:I-STATE LEAD	II-REM/FIT LEAD III-REM/FIT LEAD X IV OTHER: State Accompanies Limited On-site None FIT State Involvement		
Priority Justification and State Comments Regarding: X PASIFollow-up SIRPSHRS			
An inspection of this property was made on October 23, 1987, by IDEM personnel along with officials from the Avon School Corporation. According to Dr. Thomas Terry, superintendent, no dumping of any hazardous materials has ever taken place on the property. The inspection did not reveal any evidence of dumping. At this time the State is recommending no further action regarding this site.			
STATE INVOLVEMENT			
Responsib	sments Site Inspection follow-up Site Inspection ole Party Search Hazard Ranking System (HRS)		
* COMPLETE DOCUMENTS (C) REVIEW DOCUMENTS (R)			
Prepared by: Alan Fre Activity Time: 16			

15 4/27 80